

Two 3rd Infantry Division Soldiers were killed in Iraq on 11 November 2005 at 0622 local when a collision occurred with two fuel tankers in an 18 vehicle

vehicles caught fire and the two Soldiers were trapped inside.

A 172nd Stryker BCT Soldier was killed in Iraq on 12 November 2005 at 0710 local when a Strvker vehicle in a three vehicle convoy rolled over.

A civilian contractor was killed in Kuwait on 12 November 2005 at 1100 local when he made a left turn in an M998 and a 5,000lb. water truck driven by a third country national could not stop in time and impacted the M998 on the driver's side.

An 82nd Airborne Division Soldier lost control of his motorcycle and impacted a wooden fence in Raeford, NC on

https://crc.army.mil

13 November 2005 at 1630 local. The Soldier sustained fractures of the C-5 vertebrae. lower right arm, and loss of his right foot.

A 101st Airborne Division UH-60A flew under a JLENS, cutting the Keylar optic tether line attaching the JLENS to the mobile mooring station. The JLENS free floated to 5000 feet and burst on 15 November 2005 at 1443 local in Iraq.

A Texas National Guard OH-58A lost power and impacted in a pecan tree grove near Fort Bliss, TX on 16

November 2005 at 1900 local while conducting a boarder security and support mission. All three personnel on board the aircraft were injured.

A RQ-7B Shadow had an engine failure at Fort Huachuca, AZ on 16 November 2005 at 1955 local. The RQ-7B was too low to deploy the recovery chute.





